

page 1 of 11

№ GJW2019-5062

TEST REPORT

NAME OF SAMPLE : record STA20 IP65, RED/DUO incl. VRR20, BAT16 and FEM0

CLIENT :

agtatec ag

CLASSIFICATION OF TEST : Commission Test



| № GJW2019- | ⊆ GJW2019-5062 page 2 of 11 | | |
|--|--|-------------------------|--|
| Name of sample | record STA20 IP65, RED/DUO incl. VRR20, BAT16 and FEM0 | Trade mark | 1 |
| Client | agtatec ag | Client address | Allmendstrasse 24, 8320 Fehraltorf, Switzerland |
| Manufacturer | / | Manufacturer address | / |
| Means of receiving | Sending sample | Receiving date | 2019-10-30 |
| Classifica- tion of test | Commission Test | Completing date | 2019-11-01 |
| Tested according to | IEC 60529:1989+AMD1:1999+ AMD2:2013+COR2:2015 | Test items | Degrees of protection provided by enclosure (IP65) |
| Test Conclusion: | | | |
| According to the standard of IEC 60529:1989+AMD1:1999+AMD2:2013+COR2:2015 Degrees of | | | |

protection provided by enclosures (IP code).IP65 test has been conducted on the sample. The test results are detailed on pages 5-6.

Conclusion: pass.



Approved by:Liu Gonggui

Reviewed by: Zhuang Shaohong

Tested by: Xu Liangna

Signature:

Lin Conggui

Signature:

Thuma theohong

Xulicingna Signature:

| Nº GJW2019-5062 | 2 | | page 3 of 11 | | |
|-----------------------|--|------------|--------------------|--|--|
| | 1 Basic information : | | | | |
| | Name of sample | Type/Model | Quantity of sample | | |
| | record STA20 IP65,RED/DUO incl.VRR20,BAT16 and FEM0 | / | 1 | | |
| | 2 Sample picture: | | | | |
| Sample description | | | | | |
| | Fig 1: Sample | | | | |
| | 3 Other information: | | | | |
| | / | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Remarks | | — | | | |
| | | | | | |

№ GJW2019-5062

| Tests Summary | | | | | |
|---------------|---|-----------|--|--------------|--|
| Nº | Name of sample | Test item | Test standard | Test details | |
| 1 | record STA20 IP65, RED/DUO incl. VRR20, BAT16 and FEM0 | IP65 | IEC 60529:1989+AMD1:1999+ AMD2:2013+COR2:2015 | Pages 5-6 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

№ GJW2019-5062

1 Degrees of protection provided by enclosure (IP65)

1.1 General description

According to the standard of IEC 60529:1989+AMD1:1999+AMD2:2013+COR2:2015, test has

been conducted.

1.2 Technical requirements

The object probe of 1 mm Φ 80mm length, shall have adequate clearance form hazardous parts.

After test if the enclosure is provided with drain-holes, it should be proved by inspection that any water which enters does not accumulate and that it drains away without doing any harm to the equipment.

For enclosures without drain-holes, the relevant product standard shall specify the acceptance conditions if water can accumulate to reach live parts.

1.3 Test results

| According to: IEC 60529:1989+AMD1:1999+AMD2:2013+COR2:2015, | | | | | |
|---|--|---------------|---|---------|--|
| IP Code | Test requirement | Sample No. | Test result | Verdict | |
| IP1X | The object probe, sphere of 50 mm Φ_3 shall not fully penetrate and have adequate clearance from hazardous parts. | _ | _ | Ν | |
| IP2X | The object probe, sphere of 12.5 mm Φ_{τ} shall not fully penetrate. The jointed test finger of 12 mm Φ , shall have adequate clearance from hazardous parts. | _ | | N | |
| IP3X | The object probe, sphere of 2.5 mm Φ,shall not penetrate at all and have adequate clearance from hazardous parts. | _ | _ | N | |
| IP4X | The object probe, sphere of 1 mm Φ,shall not penetrate at all and have adequate clearance from hazardous parts. | | — | N | |
| IP5X | The object probe, sphere of 1 mm Φ,shall not penetrate at all and have adequate clearance from hazardous parts. Ingress of dust is not totally prevented, but dust shall not penetrate in a quantity to interfere with satisfactory operation of the apparatus or to impair safety. | _ | — | N | |
| IP6X | The object probe, sphere of 1 mm Φ,shall not penetrate at all and have adequate clearance from hazardous parts. No ingress of dust. | 1-1 | The object probe of $1 \text{mm} \Phi \text{does} \text{not}$ penetrate the enclosure of the sample. No dust is visible in the enclosure of the sample. | Ρ | |

page 5 of 11

| № GJW2 | GJW2019-5062 page 6 of | | | of 11 |
|--------|---|-----|---|-------|
| IPX1 | In general, if any water has entered, it shall not: | _ | | Ν |
| IPX2 | • be sufficient to interfere with the correct operation of the equipment or impair | | | N |
| IPX3 | safety;deposit on insulation parts where it could | _ | _ | Ν |
| IPX4 | lead to tracking along the creepage distances; | _ | _ | Ν |
| IPX5 | reach live parts or windings not designed to operate when wet; accumulate near the cable end or enter the cable if any. If the enclosure is provided with drain-holes, it | 1-1 | No water is visible in the enclosure of the sample. | Ρ |
| IPX6 | should be proved by inspection that any water which enters does not accumulate and that it drains away without doing any harm to the | _ | _ | Ν |
| IPX7 | equipment. For enclosures without drain-holes, the | _ | — | Ν |
| IPX8 | relevant product standard shall specify the acceptance conditions if water can accumulate to reach live parts. | | | Ν |

1.4 Test equipment

| Nº | Type / Model | Equipment name | Next due calibration date |
|----|--------------|------------------------------|---------------------------|
| 1 | V021106 | The object probe finger | 2020-04-01 |
| 2 | 110314-2 | Sand And Dust Test Chamber | 2020-06-27 |
| 3 | 1191240 | Digital Push & Pull Tester | 2020-06-25 |
| 4 | 110125921 | Degrees of Waterproof tester | 2020-06-26 |

№ GJW2019-5062 **1.5 Test pictures**



Fig 2: The object probe of 1mm Φ does not penetrate the enclosure of the sample.



Fig 3: IP6X testing



Fig 4: After IP6X test

№ GJW2019-5062



Fig 5: After IP6X test, no dust is visible in the enclosure of the sample



Fig 6: After IP6X test, no dust is visible in the enclosure of the sample



Fig 7: After IP6X test, no dust is visible in the enclosure of the sample

№ GJW2019-5062

page 9 of 11



Fig 8: IPX6 testing



Fig 9: After IPX6 test, no water is visible in the enclosure of the sample



Fig 10: After IPX6 test, no water is visible in the enclosure of the sample

№ GJW2019-5062



№ GJW2019-5062

page 11 of 11

Important

- 1. The test report is invalid without the official stamp of CVC;
- 2. Any photocopies or part photocopies of the test report are forbidden without the written permission from CVC;
- 3. The test report is invalid without the signatures of Author and Reviewer;
- 4. The test report is invalid if altered;
- 5. Objections to the test report must be submitted to CVC within 15 days;
- 6. Generally, commission test is responsible for the tested samples only;
- As for the test result, "N" or "—" means "not applicable", "/ " means "not testing", "P" means "pass", and "F" means "fail".

Address: No.3,Tiantaiyi Road, Kaitai Avenue, Science City, Guangzhou, China Tel: 020 32293888 Fax: 020 32293889 Post Code: 510663 E-mail: office@cvc.org.cn http://www.cvc.org.cn